

Central Plains Elementary School- Holyrood	Wilson Elementary School	Central Plains HS/MS- Claflin
More Space for Students- Classrooms, Cafeteria, Restrooms	Air Conditioning System/Gym AC	Continue to mitigate asbestos- ceiling tile, Floor tile
Continue with Flooring Facility	Lawn Mower	water valves throughout
Gym Floor Sanded and refinished	Continue to Carpet Classrooms	Continue Flooring facility
Concrete Playground (Swamp Area)	Entry System- Rekey Locks or keyless system	AC Units- Classrooms, office area
Parking Lot	Roof leaks in multiple places- Library, secondary gym	Sprinkler System- Pract. Field
Walk in Freezer	Gym floor sanded and refinished	Space for students- Cafeteria, classroom, restrooms
Garage for vehicles with storage	Sprinkler System for front/side of school. Needs Repaired/replaced.	Gym floor sanded and refinished
Roof Repairs- Roof Leaks	Parking Lot & South Parking - Has not been sealed for 15 years.	Entry Way Upgrades
Drainage Problems in the Cafeteria	Front of gym needs painting	Visitors bleachers on the FB field
	Kitchen Floor	Lights on football field
	Restroom Floors	Continue Painting Exterior
	LED Lighting Upgrade	Gym Lights