



Fire Safety Inspection

Main Building

Complete

Flagged items

4

Actions

0

Audit Title

Main Building

Client / Site

Downsville Central School District

Conducted on

30 Aug 2023

Prepared by

Richard Shaw

Other Personnel

Ryan Vogler, DOF

Re-Inspection Required?

No

Flagged items

4 flagged

Audit / 2. Exits

2 E-2 Emergency rescue windows are free from obstructing bars, screens, grilles or classroom equipment, or if so equipped, windows must be releasable or removable from the inside without the use of a key, tool, or force greater than that needed for normal operation.

Non-Compliant

Rooms B-104, 106, 213, 220



Photo 1

Audit / 6. Housekeeping, General Operation

6 F-1 Storage in storerooms and classroom areas is orderly and restricted to items of obvious value and usefulness.

Non-Compliant

Wood shop




Photo 2

Audit / 12. Building Services and Systems

12 G-1 Electrical service and branch equipment working space is unobstructed. - F604

Non-Compliant

Band/Choir store room




Photo 3

Audit / 15. Decorative Material and Furnishings

15 A-2 Furnishings do not obstruct or obscure exits. - F807

Non-Compliant

Basement corridors




Photo 4




Photo 5

Audit

4 flagged

2. Exits

1 flagged

2 E-2 Emergency rescue windows are free from obstructing bars, screens, grilles or classroom equipment, or if so equipped, windows must be releasable or removable from the inside without the use of a key, tool, or force greater than that needed for normal operation.

Non-Compliant

Rooms B-104, 106, 213, 220



Photo 1

6. Housekeeping, General Operation

1 flagged

6 F-1 Storage in storerooms and classroom areas is orderly and restricted to items of obvious value and usefulness.

Non-Compliant

Wood shop




Photo 2

12. Building Services and Systems

1 flagged

12 G-1 Electrical service and branch equipment working space is unobstructed. - F604

Non-Compliant

Band/Choir store room




Photo 3

15. Decorative Material and Furnishings

1 flagged

15 A-2 Furnishings do not obstruct or obscure exits. - F807

Non-Compliant

Basement corridors




Photo 4




Photo 5

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5